

Release: v6.4.1

Release Date: November 2015

This firmware release is a recommended update for all users and includes the following improvements:

- Improved audio quality.
- Improved power plug and AUX detection.
- Improved power management.
- Resolves a firmware update issue using Bluetooth Utility on a Mac OSX.
- Resolves an issue with aptX Low Latency.
- General bug fixes and improved user experience.

Please refer to T7 manual for further information on product operation.